

17977

#### **IED Report**

REL TO

CLASSIFICATION: SECRET RELEASABILITY: USA,

ACGU

IED- 2011-

TRACKING NUMBER: 20111122093938SMB54382 DATE DISCOVERED: Nov-22

09:39

CALL SIGN: Jester REPORTING UNIT: 752

PRIMARY SAFE 38SMB5440917894 SECONDARY SAFE Report

AREA(MGRS):

AREA(MGRS):

AREA(MGRS):

MGRS: 38SMB5438217977 EVENT TYPE: Explosi

: 385MB543821/9// EVENTIYPE: on

COALITION:

KIA: WIA: KIA: WIA: KIA: WIA:

O O O O O O O

Equipment Used 1

EQUIPMENT USED TYPE: Vehicle EQUIPMENT USED NAME: JERRV

Equipment Used 2

EQUIPMENT USED TYPE: PPE EQUIPMENT USED NAME: Other

Equipment Used 3

EQUIPMENT USED TYPE: Crew EQUIPMENT USED NAME: Other

Team Data

23-November-11 Page 1of 4



SERVICE AFFILIATION: USA

EOD NOTIFICATION: 2011-Nov-22 09:40

EOD FOB DEPARTURE: 2011-Nov-22 09:55 EOD SCENE ARRIVAL: 2011-Nov-22 10:13

EOD SCENE
DEPARTURE:

2011-Nov-22 11:25 EOD MISSION

COMPLETE:

2011-Nov-22 11:40

Site Data

SITE MARKED: No

MARKING DETAILS: Not Reported

CIVILIAN ACTIVITY: No Civilians Present - Area Usually Vacated

REFERENCE POINT: No

AIMING POINT DETAILS: Not Reported

FIRING POINT DETAILS: Not Reported

FIRING POINT MGRS: Not Reported

LIGHT CONDITIONS: Daytime

WEATHER: Clear

ROUTE PATROL: Unknown

LAST TIME ROUTE

CLEARED:

**Not Reported** 

ANALYSIS: Not Reported

Devices

Device 1

**DEVICE DESCRIPTION: Not Reported** 

MGRS: 38SMB5437917940

PLACEMENT: LOCATION: Road - Right

Side

152 08/08/2018

CONTAINER: Unknown CONTAINER SUB-TYPE: Not Reported

23-November-11 Page 2of 4

USCENTCOM FOIA 17-0112



HOW DEVICE WAS FOUND: Detonation WHO FOUND DEVICE: Not Applicable

ACTION TAKEN: Post Blast

**EXPLOSIVE EFFECT:** Fragmentation

Blast

MAIN CHARGE CONFIGURATION: Directional-EFP

CASUALTIES: No SUICIDE DEVICE: No FIRST RESPONDER TARGETED: No

POST BLAST: Yes PARTIAL BUILD: No

**Targets** 

TARGET PRECEDENCE: Primary AFFILIATION: Coalition

COUNTRY: USA - UNITED TARGET TYPE: Military

STATES

DETAILS: Convoy INTENDED EFFECT: Anti-Armor

**DESCRIPTION:** Not Reported

Initiators

TYPE: Unknown INITIATION SUB-TYPE: Not

Reported

INITIATION DETAIL: Not INITIATOR: Unknown

Reported

ARMING: Not DTMF: No

Rep. rted

MAKE: Not MODEL: Not

Reported Reported

RECEIVER REMOTED: Unknown RECEIVER REMOTED DISTANCE(M): 0

Munitions

CATEGORY: UBE MUNITIONS TYPE: Unknown

NAME: Not Reported QUANTITY: Not Reported

COUNTRY: UC - UNKNOWN

COUNTRY

WEIGHT: SIZE: Not Reported Not

Reported

23-November-11 Page 3 of 4

USCENTCOM FOIA 17-0112 153 08/08/2018



NET EXPLOSIVE WEIGHT: 30 lb

LOT NUMBER: Not Reported SERIAL NUMBER: Not Reported

**DETAILS:** Not Reported

Fusing

DETAILS: Not Reported COUNTRY: UC - Unknown Country

Render Safe

RSP: Not Attempted RENDER SAFE DETAILS: Not Reported

23-November-11 Page 4of 4

USCENTCOM FOIA 17-0112 154 08/08/2018



#### \*\*\*\*SIGACT CLOSED\*\*\*\*

#### **SIGACT Report**

TITLE: (EXPLOSIVE HAZARD) IED EXPLOSION RPT (Directional IED) 2-5 CAV,

1-1 AAB IVO (ROUTE MSR TAMPA): 0 INJ/DAM

TRACKING NUMBER: 20111122093938SMB5438217977

REPORT PRECEDENCE: Flash

CLASSIFICATION: SECRET RELEASABILITY: REL TO USA, FVEY

REPORTING UNIT NAME: USD-C G3 SIGACT

MANAGER

REPORT SOURCE:

Coalition

#### **SPOT Section**

UNIT NAME INVOLVED: 2-5 CAV, 1-1 AAB CALL SIGN: Not Reported

TYPE OF INVOLVED UNIT: CF INVOLVED UNIT ACTIVITY: Other

INCIDENT REPORTED BY: Coalition Forces BATTLESPACE LEAD: Coalition

TIP REPORTED BY: Not Reported DTG CREATED (LOCAL): 2011-11-22

11:47:17

DTG OF INCIDENT (LOCAL): 2011-11-22 DTG UPDATED (LOCAL): 2011-11-23

09:39:00 16:39:37

Location

MGRS: 38SMB5437917940 ROUTE: MSR TAMPA

**Events** 

EVENT TYPE: Explosive Hazard MODES OF ATTACK: Directional IED

**EVENT CATEGORY:** IED Explosion

23-November-11 Page 1of 6
SECRET//REL TO USA, FVEY

USCENTCOM FOIA 17-0112

PRIMARY INTENDED OUTCOME: Anti-Armor

SUICIDE?: No EFFECTIVE HIT?: No

COORDINATED ATTACK: No

COMPLEX ATTACK: No

COUNTER ATTACK: No

MEDEVAC REQUESTED: No

BLOWN IN PLACE: No

SUMMARY: USF REPORT

SUMMARY: AT 22 0939 NOV 11, AN IED DETONATED ON THE LEAD CAIMAN OF A 3/B/2-5 CAV CIED PATROL TRAVELING SOUTH ON MSR TAMPA IN BABIL. THE PATROL REPORTED NO CASUALTIES AND 1 X CAIMAN DAMAGED THAT REQUIRED RECOVERY. MSR TAMPA WAS TURNED BLACK. PREDATOR MOVED TO THE SITE TO PROVIDE OVERWATCH. IP ONSITE PROVIDED ADDITIONAL SECURITY. 2-5 CAV REPORTED THAT IMMEDIATELY AFTER THE BLAST, 4 X LN FLED SITE TO A HOUSE IN THE AREA. SHADOW PROVIDED OVERWATCH OF THE HOUSE. AN ADDITIONAL QRF ELEMENT AND ISF RESPONDED TO THE HOUSE, CORDONED THE AREA, AND CONDUCTED A COMBINED SEARCH WITH NSTR. EOD CONDUCTED PBA AT THE BLAST SITE AND ASSESSED THAT THE BLAST WAS THE RESULT OF AN EFP. THE SITE WAS CLEARED AND MSR TAMPA WAS CHANGED FROM BLACK TO AMBER. 3/B/2-5 CAV, QRF, EOD, AND REVOVERY RTB COS KALSU AT 1147.

1/1 AAB S2 ASSESSMENT: BASED ON THE LOCATION AND THE TYPE OF MUNITION USED. THIS ATTACK WAS LIKELY CONDUCTED BY

(b)	(1)1.4c, (b)(6)	
(b)(1)1	.4c	OF
INITIATION SYSTEM AND NO	COMMAND WIRE	FOUND ON SCENE IS
CONSISTENT WITH	(b)(1)1.4c, (b)	(6)
(b)(1)1	1.4c	
(b)(1)1.4c BETWEEN CHE	CKPOINTS 9A AND	12A ON MSR TAMP
(b)(1)1.4c , IT IS LIKELY T	HAT USF C-IED PR	ESENCE IN THE AREA
HAS CAUSED HIM TO CHANGE	E LOCATIONS.	
USD-C G2 ASSESSMENT:	(b)(1)1.	4c
(b)(	(1)1.4c	
(b)(1)1.4c		PATROL WHILE

23-November-11 Page 2of 6



(b)(1)1.4c		
RESULTED IN ONE MRAP DAMAGED BUT NO C	ASUALTIES.	(b)(1)1.4c
APPROXIMATELY 400M TO THE NORTH OF	(b)(1)1.4c	AND
DAMAGED BUT NO CASUALTIES. TODAY'S ATTA	ACK OCCURRI	ED
TRAVELING NORTH ON TAMPA RESULTING IN	ONE CAIMAN	

USF CONVOYS TRAVELING ON MSR TAMPA USING IEDS. HOWEVER, THERE IS NO INFORMATION OR REPORTING AT THIS TIME TO INDICATE INDIVIDUAL(S) OR GROUP RESPONSIBLE FOR THIS ATTACK.

EOD ASSESSMENT: 752/2/2 RESPONDED TO A PBA AT 38S MB 54379 17940 ISO 1/1 CAV. TEAM ARRIVED ON SCENE AND THE BARBARIAN BLUE COMMANDER REPORTED THAT WHILE TRAVELING SOUTH ON MSR TAMPA, THERE WAS A DETONATION NEXT TO THE LEAD VEHICLE ON THE WEST SIDE OF THE ROAD. VEHICLE PUSHED THROUGH THE BLAST AREA AND STOPPED APPROXIMATELY 100M FROM THE BLAST SEAT, TEAM PERFORMED A RECON AND EXPLOITED THE SITE, TEAM DISCOVERED THAT THE BLAST DAMAGE ON THE VEHICLE WAS THE BLAST SEAT WAS 20' (b)(1)1.4q FROM THE ROAD AND MEASURED 40" X 32" X 8" DEEP. THE BLAST SEAT WAS CONSISTENT WITH APPROXIMATELY 30 POUNDS OF UNKNOWN BULK EXPLOSIVES. TEAM DISCOVERED NO FURTHER EVIDENCE TO SUGJEST DEVICE INITIATION AND FOUND NO FURTHER EXPLOSIVE HAZARDS.

BDA:

1 X CAIMAN DAMAGED

CLOSED

ENEMY:				COALITION:	
KIA:	WIA:	DET:	KIA:	WIA:	ABD:
0	0	0	0	0	0

CIVILIAN:				HOST NATION:	
KIA:	WIA:	ABD:	KIA:	WIA:	ABD:
0	0	0	0	0	0

#### **CCIR Status**

23-November-11 Page 3 of 6 SECRET//REL TO USA, FVE

USCENTCOM FOIA 17-0112

157 08/08/2018



SUMMARY: USF-I DCG(O) IR 17: Any attack utilizing RKG-3, EFP, SVBIED and/or

PBIED

GROUP: USD-C G3 SIGACT MANAGER

#### **Capture Details**

#### **Casualty Details**

#### Target(s) of Attack

PRECEDENCE: Primary TYPE: Coalition

AFFILIATION: Coalition SECT: Unknown

DETAILS: Convoy NATIONALITY: IRAQ

STATUS: Damaged

DESCRIPTION: Not Reported

#### **Indirect Fire Information**

#### Vehicle/Convoy Details

NUMBER OF VEHICLES: 0

DISTANCE BETWEEN VEHICLES: 0 Meters

CONVOY SPEED: 0 MPH

NEAREST ECM DIST TO IED: 0 Meters

NEAREST ECM DIST TO VEHICLE STRUCK: 0 Meters

OTHER COUNTERMEASURES ON VEHICLE STRUCK: Not Reported

23-November-11 Page 4of 6

USCENTCOM FOIA 17-0112 158 08/08/2018



VEHICLE SUMMARY:	Not Reported

DRUGREP Details
 FACILITY TYPE: Not Reported
Drugs Found
Chemicals Found
Equipment Found
A TO
0

Reintegration Details					
REINTEGRATION OPEN:			No		
REINTEGRATION OPEN COMME	NTS:		No		
NUMBER OF REINTEGRATEES:			0		
	FOLLOW UP DATES	COMPLETED	COMPLETED DATE		
VETTING DATE:	Not Reported	No	Not Reported		
COMMUNITY TALK DATE:	Not Reported	No	Not Reported		
REINTEGRATION DATE:	Not Reported	No	Not Reported		

23-November-11 Page 5of 6

USCENTCOM FOIA 17-0112 159 08/08/2018



7 DAY FOLLOW UP: Not Reported No Not Reported

30 DAY FOLLOW UP: Not Reported No Not Reported

60 DAY FOLLOW UP: Not Reported No Not Reported

90 DAY FOLLOW UP: Not Reported No Not Reported

180 DAY FOLLOW UP: Not Reported No Not Reported

REINTEGRATION CLOSED: No REINTEGRATION CLOSED REASON: Not

Reported

REINTEGRATION CLOSED COMMENTS:

23-November-11 Page 6of 6

SECRET//REL TO USA, FVEY

USCENTCOM FOIA 17-0112 160 08/08/2018



(752 | 2 | 2)

220940CNOV11

1/1 CAV SUPPORTED BCT

(b)(3), (b)(6)
TEAM LEADER

2/5/1/1

ON SCENE COMM

38SMB5437917940 MGRS GRID LOCATION MSR TAMPA MSR

Sout DIRECTION OF

IED

TYPE OF REPORT

Explosion EVENT CATEGORY Othe

SIGACT #: 20111122093 .38SM 5438217977

CIDNE #: IED-2011112207 938SMB5438217977


CCIR: USD-C15,18 DCG-O

	CF	LN	IA/IP/NP	E	U.S. Civilian	Coalition
KIA	0	0	0	Ō	0	
WIA	0 USCENTCOM	<b>O</b> FOIA 17-0112	0	0	0	161 0

SECRET // REL TO USA, ACGU







USCENTCOM FOIA 17-0112 162 0



## Aerial / Map View of Site



#### Time

**EOD Notification:** 

**EOD FOB Departure:** 

**EOD Scene Arrival:** 

**EOD Scene Departure:** 

**EOD Mission Complete:** 




USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU



# Scene Diagram



USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU



#### Narrative / Background

(SECRET // REL TO USA, FVEY) 752/2/2 responded to a PBA at 38S MB 54379 17940 ISO 1/1 CAV. arrived on scene and the Barbarian Blue Commander reported that while traveling south on MSR there was a detonation next to the lead vehicle on the west side of the road. Vehicle pushed throublast area and stopped approximately 100m from the blast seat. Team performed a recon and expethe site. Team discovered that the blast damage to the vehicle was consistent with a blast seat was 20' from the road and measured 40" x 32" x 8" deep. The blast seat was consistent approximately 30 pounds of unknown bulk explosives. Team discovered no further evidence to sidevice initiation and found no further explosive hazards. MC: 221140CNOV11.

USCENTCOM FOIA 17-0112 165 0



#### **Evidence List**

Item/Bag #	Quantity	Evidence		
1		(b)(1)1.4c	-8	

USCENTCOM FOIA 17-0112 166 0



# Photographs of Scene




Aerial View

USCENTCOM FOIA 17-0112 167 0



# Photographs of Scene



Return to

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU



# Photographs of Scene



North

USCENTCOM FOIA 17-0112



# Photographs of Scene



East

USCENTCOM FOIA 17-0112 170 0



# Photographs of Scene



South

USCENTCOM FOIA 17-0112 171 0



# Photographs of Scene



West

USCENTCOM FOIA 17-0112 172 0



## Photographs of Scene



Blast seat

USCENTCOM FOIA 17-0112 173 0



# Photographs of Scene

Blast damage

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU



# Photographs of Scene



(b)(1)1.4c

found on tire rim

USCENTCOM FOIA 17-0112 175 0



## Photographs of Scene



Blast damage

USCENTCOM FOIA 17-0112 176 0

SECRET // REL TO USA, ACGU



## Photographs of Scene



EFP entry point on hood

USCENTCOM FOIA 17-0112



## Photographs of Scene




EFP Direction of travel

USCENTCOM FOIA 17-0112 178 0

SECRET // REL TO USA, ACGU





Damage on driver side from fragments traveling in engine compartment

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU



## Photographs of Scene



Damage to (b)(1)1.49

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU



## Photographs of Scene




Damage to (b)(1)1.4g

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU



## Photographs of Scene



Damage to (b)(1)1.4g

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU



## Photographs of Scene



Damage to (b)(1)1.4g

USCENTCOM FOIA 17-0112 183 0



## Photographs of Scene



Piece of copper recovered from (b)(1)1.49

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU



## Photographs of Scene



Vehicle damage

USCENTCOM FOIA 17-0112 185 0



# Photographs of Scene



Damage to light

USCENTCOM FOIA 17-0112 186 0



## Photographs of Scene



Vehicle damage

USCENTCOM FOIA 17-0112



## Photographs of Scene



Damage to TC window

USCENTCOM FOIA 17-0112 188 0

SECRET // REL TO USA, ACGU



## Photographs of Scene



DVE cable servered

USCENTCOM FOIA 17-0112 189 0

SECRET // REL TO USA, ACGU



# Photographs of Scene



(b)(1)1.4c

on gunners ammo can

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU



## Photographs of Scene



Impact on gunners chicken shield

USCENTCOM FOIA 17-0112 191 0



## Photographs of Scene



(b)(1)1.4c

recovered from vehicle

USCENTCOM FOIA 17-0112 192 0